



1. Surface mounted track profile joint installation- straight



2. Power connector installation

- 1.) Locate the cable entry hole at the end of the track profile. The power connector is used to connect a 24V DC constant voltage power supply to operate the track system (Figure 2).
- 2.) Feed the power cable from the driver through the entry hole on the track profile and connect it to the output terminal of the constant voltage driver. Connect the input side of the driver to the 110V/240V mains power (Figure 3).
- 3.) Once the wiring is complete, insert the power connector into the track profile (Figure 4).

